

Whirl Pool/Spas/Splash Pads
last updated 18-Nov-20

Premises Name	Address	Type of Inspection	Inspection Date	Summary of Infractions	Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	13-Feb-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	24-May-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Sep-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	20-Dec-18	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	24-Dec-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	11-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	27-Aug-19	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	27-Aug-19	Required notice(s) are provided and accurate	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Safety equipment available and in good repair	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	pH is within range of 7.2 to 7.8	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	6-Nov-20		Satisfactory - No Action(s) Taken
Cache Bay Splash Park	Cache Road, Cache Bay ON	Routine Inspection	13-Jul-20	Sign(s) posted setting out health and safety rules for spray/splash pad users and notifying parents or guardians to supervise their children at all times	Re-inspection Scheduled
Cache Bay Splash Park (Splash Pad)	55 Cache Street, Cache Bay ON	Routine Inspection	31-Aug-20		Satisfactory - No Action(s) Taken

Callander - Splash Pad	Main St, Callander ON P0H 1H0	Routine Inspection	21-Jun-19		Satisfactory - No Action(s) Taken
Callander - Splash Pad	Main Street Callander ON P0H 1H0	Routine Inspection	21-Jun-19		Satisfactory - No Action(s) Taken
Callander - Splash Pad	Main Street, Callander ON P0H 1H0	Routine Inspection	30-Jul-19		Satisfactory - No Action(s) Taken
Callander Splash Pad	Main Street, Callander ON	Routine Inspection	27-Aug-18		Satisfactory - No Action(s) Taken
Callander Splash Pad	Main Street, Callander ON	Routine Inspection	27-Aug-18		Satisfactory - No Action(s) Taken
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	23-Feb-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	23-Feb-18	Dressing rooms, water closets, and/or shower facilities maintained in sanitary condition and free from potential hazards	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	Spa, mechanical, and emergency equipment operational and maintained in a safe/sanitary condition	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	pH is within range of 7.2 to 7.8	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	Oxidation Reduction Potential (ORP) value is a minimum of 700 mV (if equipped with automatic sensing devices)	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	Other records signed and completed	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	Operator designated and trained	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Routine Inspection	4-Oct-18	Premises is maintained free from every condition that may be a health hazard	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Spa, mechanical, and emergency equipment operational and maintained in a safe/sanitary condition	Closure

Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Daily records completed and signed	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Oxidation Reduction Potential (ORP) value is a minimum of 700 mV (if equipped with automatic sensing devices)	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Manual tests conducted ½ hour before spa opens every hour spa is open for use	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Other records signed and completed	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Safety equipment available and in good repair (inner horizontal dimension >3m)	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Operator designated and trained	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Premises is maintained free from every condition that may be a health hazard	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	5-Oct-18	Deck and walls maintained in a sanitary condition and free from hazards	
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound P2A 2G5	Re-inspection	29-Oct-18	Operator designated and trained	Re-inspection Scheduled
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	8-Mar-18	pH is within range of 7.2 to 7.8	Corrected During Inspection
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	21-Sep-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Closure
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	21-Sep-18	pH is within range of 7.2 to 7.8	Closure
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	21-Sep-18	Premises is maintained free from every condition that may be a health hazard	Closure
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	21-Sep-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled
Lakeside at Rocky Crest	149 Hamer Bay Road, MacTier ON POC 1H0	Routine Inspection	14-Mar-19	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Lakeside at Rocky Crest	149 Hamer Bay Road, MacTier ON POC 1H0	Routine Inspection	14-Mar-19	pH is within range of 7.2 to 7.8	Corrected During Inspection

Lakeside at Rocky Crest	149 Hamer Bay Road, MacTier ON POC 1H0	Routine Inspection	14-Mar-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	24-Jun-19		Satisfactory - No Action(s) Taken
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	29-Aug-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	29-Aug-19	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	30-Oct-19	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Lakeside at Rocky Crest	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	12-Mar-20		Satisfactory - No Action(s) Taken
Make a Splash for Stacey	Sundridge Muncipal beach	Routine Inspection	27-Jun-19		Satisfactory - No Action(s) Taken
Make a Splash for Stacey	Sundridge Muncipal beach	Routine Inspection	29-Jul-19		Satisfactory - No Action(s) Taken
Mattawa Splash Pad	250 Timmins St, Mattawa ON	Routine Inspection	17-Sep-19		Satisfactory - No Action(s) Taken
Northridge Inn & Resort	712 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	17-May-18		Satisfactory - No Action(s) Taken
Northridge Inn & Resort	712 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	27-Jun-18		Satisfactory - No Action(s) Taken
Northridge Inn & Resort	713 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	17-May-19	Other records signed and completed	Corrected During Inspection
Northridge Inn & Resort	713 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	30-Jul-19		Satisfactory - No Action(s) Taken
Northridge Inn & Resort	712 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	17-Sep-19		Satisfactory - No Action(s) Taken
Northridge Inn & Resort	712 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	26-Jun-20		Satisfactory - No Action(s) Taken
Northridge Inn & Resort	712 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	24-Aug-20	every bather shall take a cleansing shower/bath with soap and warm water before entering deck	Re-inspection Scheduled
Northridge Inn & Resort	712 South Bernard Lake Road, Sundridge ON P0A 1Z0	Routine Inspection	24-Aug-20	cyanuric acid not used in public spa	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Point au Baril ON P0G 1K0	Routine Inspection	22-Jun-18		Satisfactory - No Action(s) Taken
Pleasant Cove Resort	97 North Shore Road, Pointe Au Baril ON P0G 1K0	Routine Inspection	17-Sep-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Re-inspection Scheduled

Pleasant Cove Resort	97 North Shore Road, Pointe Au Baril ON POG 1K0	Routine Inspection	17-Sep-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe Au Baril ON POG 1K0	Re-inspection	18-Sep-18		Satisfactory - No Action(s) Taken
Quality Inn- Whirlpoo/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	25-Apr-19		Satisfactory - No Action(s) Taken
Quality Inn- Whirlpoo/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	25-Apr-19		Satisfactory - No Action(s) Taken
Quality Inn- Whirlpoo/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	12-Sep-19	Operator designated and trained	Re-inspection Scheduled
Quality Inn- Whirlpoo/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	12-Sep-19	If equipped with an automatic sensing device, manual tests conducted at least 1/2 hour before the spa opens and parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual, water clarity and water temperature)	Re-inspection Scheduled
Quality Inn- Whirlpoo/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	17-Oct-19	Operator designated and trained	Re-inspection Scheduled
Quality Inn- Whirlpoo/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	22-Jan-20		Satisfactory - No Action(s) Taken
Quiet Bay Log Motel & Café	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Feb-18	Manual tests conducted ½ hour before spa opens every hour spa is open for use	Re-inspection Scheduled
Quiet Bay Log Motel & Café	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Feb-18	Spa water heater equipped with an operational tamper-proof upper limit cut-off switch	Closure
Quiet Bay Log Motel & Café	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Feb-18	Provide fully supplied first aid box	Corrected During Inspection
Quiet Bay Log Motel & Café	5333 Highway 124, Magnetawan ON P0A 1P0	Re-inspection	15-Feb-18		Satisfactory - No Action(s) Taken
Quiet Bay Log Motel & Café	5333 Hwy 124, Magnetawan ON P0A 1P0	Routine Inspection	12-Jun-18		Satisfactory - No Action(s) Taken
Quiet Bay Log Motel & Café	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	14-Sep-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection

Ramada Pinewood Park Resort	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	8-Jan-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-May-19	pH is within range of 7.2 to 7.8	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	9-Mar-18		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Jun-18		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Sep-18		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Chemical feeder is used to administer chlorine, chlorine compound or a bromine compound	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Continuous operation of all equipment and chemical feeders	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Spa with automatic sensing device tested manually ½ hour before spa opens and at least once more during operational day	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Spa drained and refilled in accordance with prescribed formula in Regulation (spa <4000L)	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Oxidation Reduction Potential (ORP) value is a minimum of 700 mV (if equipped with automatic sensing devices)	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Manual tests conducted ½ hour before spa opens every hour spa is open for use	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Daily records completed and signed	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Other records signed and completed	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Operator designated and trained	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	27-Dec-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Closure

Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	27-Dec-18	Oxidation Reduction Potential (ORP) value is a minimum of 700 mV (if equipped with automatic sensing devices)	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Complaint	12-Feb-19	Water clarity satisfactory	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Complaint	12-Feb-19	Spa drained and refilled in accordance with prescribed formula in Regulation (spa <4000L)	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	14-Feb-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	29-May-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	29-May-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Aug-19	Clock installed in conspicuous location	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Aug-19	Free available chlorine (FAC) or total bromine within range of 5 - 10 ppm	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Aug-19	If not equipped with an automatic sensing device, manual tests conducted 1/2 hour before the spa opens and at least every 2 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual, water clarity and water temperature)	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Aug-19	Daily records completed and signed	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Aug-19	Emergency telephone sign posted with complete list of emergency contacts	
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	11-May-18	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	11-May-18	Hydro-massage jet fittings equipped with timing device	Closure

Rocky Crest Resort	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	11-May-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	11-May-18	Emergency telephone is present and operational	Closure
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON POC 1H0	Routine Inspection	27-Sep-18		Satisfactory - No Action(s) Taken
Rocky Crest Resort	20 Barnwood Drive, Mactier ON POC 1H0	Routine Inspection	17-May-19	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Rocky Crest Resort	20 Barnwood Drive, Mactier ON POC 1H0	Routine Inspection	17-May-19	Daily records completed and signed	Re-inspection Scheduled
Rocky Crest Resort	20 Barnwood Drive, Mactier ON POC 1H0	Routine Inspection	17-May-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Rocky Crest Resort	20 Barnwood Drive, Mactier ON POC 1H0	Routine Inspection	9-Aug-19	Free available chlorine (FAC) or total bromine within range of 5 - 10 ppm	Corrected During Inspection
Rocky Crest Resort	20 Barnwood Drive, Mactier ON POC 1H0	Routine Inspection	9-Aug-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Rocky Crest Resort	20 Barnwood Drive, Mactier ON POC 1H0	Routine Inspection	9-Aug-19	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	21-Feb-18		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-Jun-18	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-Jun-18	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Re-inspection	14-Jun-18	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Re-inspection	1-Aug-18		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	6-Sep-18	pH is within range of 7.2 to 7.8	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	6-Sep-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Nov-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Nov-18	pH is within range of 7.2 to 7.8	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	15-Feb-19	Suction system equipped with a vacuum relief mechanism	Closure

Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	15-Feb-19	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Re-inspection Scheduled
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	15-Feb-19	Other records signed and completed	Re-inspection Scheduled
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Re-inspection	21-Feb-19	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-May-19		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	24-Jul-19	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	4-Nov-19	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Sturgeon Falls Spray Park	Bay View Road, Sturgeon Falls ON	Routine Inspection	13-Jul-20		Satisfactory - No Action(s) Taken
Sturgeon Falls Spray Park (Splash Pad)	Lot 82 and Lot 83 Plan 12, Sturgeon Falls ON P2B 3L3	Routine Inspection	31-Aug-20		Satisfactory - No Action(s) Taken
Super 8 Parry Sound	1 JR Lane, Seguin ON P2A 2W8	Routine Inspection	1-Mar-18		Satisfactory - No Action(s) Taken
Super 8 Parry Sound	1 JR Lane, Seguin ON P2A 2W8	Routine Inspection	21-Sep-18		Satisfactory - No Action(s) Taken
Super 8 Parry Sound	1 Jolly Roger Lane	Re-inspection	8-Mar-19	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Super 8 Parry Sound	1 Jolly Roger Lane	Re-inspection	8-Mar-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Super 8 Parry Sound	1 Jolly Roger Lane	Re-inspection	8-Mar-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	27-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	27-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	12-Sep-19	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	12-Sep-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	12-Sep-19	Daily records completed and signed	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	12-Sep-19	Operator designated and trained	Corrected During Inspection

Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	5-Dec-19	Free available chlorine (FAC) or total bromine within range of 5 - 10 ppm	Closure
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	5-Dec-19	pH is within range of 7.2 to 7.8	Closure
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Re-inspection	6-Dec-19	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Super 8 Parry Sound	1 J R Ln Seguin ON P2A 2W8	Routine Inspection	24-Feb-20	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
The Family of Rotary Splash Pad	100 Ferguson Street, North Bay ON P1B 1W8	Routine Inspection	18-Jun-20		Satisfactory - No Action(s) Taken
The Family of Rotary Splash Pad	100 Ferguson Street, North Bay ON P1B 1W8	Routine Inspection	31-Aug-20		Satisfactory - No Action(s) Taken
Tom Rae Lodge	RR#1 Nipissing ON P0H 1W0	Routine Inspection	31-Aug-18		Satisfactory - No Action(s) Taken
Tom Rae Lodge	RR 1-Lot 14, Concession 13 Nipissing	Routine Inspection	10-Jul-19		Satisfactory - No Action(s) Taken
Tom Rae Lodge	RR 1-Lot 14, Concession 13 Nipissing ON P0H 1W0	Routine Inspection	15-Aug-19	Free available chlorine (FAC) or total bromine within range of 5 - 10 ppm	Corrected During Inspection
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Hydro-massage jet fittings equipped with timing device	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Spa, mechanical, and emergency equipment operational and maintained in a safe/sanitary condition	Corrected During Inspection
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Free available chlorine (FAC) or total bromine within range of 5 – 10 mg/L	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Other records signed and completed	Re-inspection Scheduled
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Emergency telephone is present and operational	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Premises is maintained free from every condition that may be a health hazard	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jun-18	Operator designated and trained	Re-inspection Scheduled
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	25-Jun-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled

Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	25-Jun-18	Spa drained and refilled in accordance with prescribed formula in Regulation (spa <4000L)	Corrected During Inspection
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	25-Jun-18	Hydro-massage jet fittings equipped with timing device	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	25-Jun-18	Suction system equipped with a vacuum relief mechanism	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	25-Jun-18	Premises is maintained free from every condition that may be a health hazard	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	25-Jun-18	Operator designated and trained	Re-inspection Scheduled
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	5-Jul-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	5-Jul-18	Hydro-massage jet fittings equipped with timing device	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	5-Jul-18	Premises is maintained free from every condition that may be a health hazard	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	16-Aug-18		Satisfactory - No Action(s) Taken
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	21-Sep-18	Spa water heater equipped with an operational tamper-proof upper limit cut-off switch	Closure
Travelodge - Whirlpool/Spa	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	21-Sep-18	Hydro-massage jet fittings equipped with timing device	Closure
Verner Splash Pad	11790 Hwy 64, Verner ON P0H 2M0	Routine Inspection	14-Jun-18		Satisfactory - No Action(s) Taken
Verner Splash Park	11790 Hwy 64 Verner, ON P0H 2M0	Routine Inspection	24-Aug-18		Satisfactory - No Action(s) Taken
Verner Splash Park	11790 Hwy 64 Verner, ON P0H 2M0	Routine Inspection	24-Aug-18		Satisfactory - No Action(s) Taken
Verner Splash Park	11790 Hwy 64, Verner ON P0H 2M0	Routine Inspection	25-Jun-19		Satisfactory - No Action(s) Taken
Verner Splash Park	11790 Hwy 64, Verner ON P0H 2M0	Routine Inspection	14-Aug-19		Satisfactory - No Action(s) Taken

Verner Splash Park	11790 Hwy 64, Verner ON P0H 2M0	Routine Inspection	13-Jul-20	Sign(s) posted setting out health and safety rules for spray/splash pad users and notifying parents or guardians to supervise their children at all times	Re-inspection Scheduled
--------------------	---------------------------------	--------------------	-----------	---	-------------------------