

**Public Pools**

last updated 27-Oct-21

Premises Name	Address	Type of Inspection	Inspection Date	Summary of Infractions	Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	21-Jun-18		Satisfactory - No Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	25-Jul-18		Satisfactory - No Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	17-Jun-19		Satisfactory - No Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	9-Aug-19		satisfactory - No Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	18-Jun-20	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	18-Jun-20	Records retained for one year	Re-inspection Scheduled
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	18-Jun-20	Written emergency and operational procedures & instructions available at the pool	Re-inspection Scheduled
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	10-Jul-20		Satisfactory - No Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	24-Aug-20		Satisfactory - No Action(s) Taken
Almaguin Campground	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	17-Jun-21		Satisfactory - No Action(s) Taken
Armishaw Pool	419 Owl Lake Road, Katrine ON P0A 5G4	Routine Inspection	12-Aug-20		Satisfactory - No Action(s) Taken
Armishaw Pool	149 Hamer Bay Road, Macteir, ON POC 1H0	Routine Inspection	28-Jun-21	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Armishaw Pool	149 Hamer Bay Road, Macteir, ON POC 1H0	Routine Inspection	28-Jun-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON POC 1H0	Routine Inspection	6-Jul-18	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Re-inspection Scheduled
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON POC 1H0	Routine Inspection	6-Jul-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Re-inspection Scheduled

Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	6-Jul-18	Emergency telephone sign posted with complete list of emergency contacts	Re-inspection Scheduled
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	6-Jul-18	"Pool Rules" notices displayed with complete information	Re-inspection Scheduled
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Re-inspection	9-Jul-18		Satisfactory - No Action(s) Taken
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	28-Jun-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	28-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	28-Jun-19	Depth markings present in appropriate locations	Re-inspection Scheduled
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	28-Jun-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	28-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	28-Jun-19	Depth markings present in appropriate locations	Re-inspection Scheduled
Armishaw Pool at Rocky Crest	149 Hamer Bay Road, Mactier, ON P0C 1H0	Routine Inspection	9-Aug-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	13-Feb-18	Depth markings present in appropriate locations	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	7-Mar-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	24-May-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Sep-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	20-Dec-18		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	11-Jun-19		Satisfactory - No Action(s) Taken

Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	27-Aug-19	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	27-Aug-19	Safety supervision requirements met	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	27-Aug-19	Depth markings present in appropriate locations (for all pools and spas >3 m in horizontal dimension)	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Total bromine (Br) residual within range of 2-4 ppm	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Safety supervision requirements met	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Shower signs posted at each shower and every entrance to the deck used by bathers	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	3-Dec-19	Safety equipment available and in good repair	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	18-Feb-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	18-Feb-20	Shower signs posted at each shower and every entrance to the deck used by bathers	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	5-Mar-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	10-Mar-20		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	12-Jun-20	Total bromine (Br) residual within range of 2-4 ppm	Re-inspection Scheduled

Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	12-Jun-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	16-Jun-20	Total alkalinity within range of 80-120 ppm	
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	Water clarity satisfactory	Closure
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	Total bromine (Br) residual within range of 2-4 ppm	Closure
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	pH is within range of 7.2 to 7.8	Closure
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	Safety equipment available and in good repair	Corrected During Inspection
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	5-Nov-20	Premises is maintained free from every serious condition that may be a health hazard	Closure
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Re-inspection	6-Nov-20		Satisfactory - No Action(s) Taken
Best Western Hotel	700 Lakeshore Drive, North Bay ON P1A 2G4	Routine Inspection	19-Jul-21	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Bowey's West Nipissing Resort Marina	10448 Hwy 64, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-20		Satisfactory - No Action(s) Taken
Bowhey's West Nipissing Resort Marina	10448 Hwy 64, Lavigne ON P0H 1R0	Routine Inspection	25-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Bowhey's West Nipissing Resort Marina	10448 Hwy 64, Lavigne ON P0H 1R0	Routine Inspection	24-Jul-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Bowhey's West Nipissing Resort Marina	10448 Hwy 64, Lavigne ON P0H 1R0	Routine Inspection	24-Jul-19	Daily records completed and signed	Corrected During Inspection
Bowhey's West Nipissing Resort Marina - Swimming Pool	10448 Hwy 64, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-21	Black disc (150 mm in diameter) on white background affixed to bottom of pool at its deepest point	Re-inspection Scheduled
Bowhey's West Nipissing Resort Marina - Swimming Pool	10448 Hwy 64, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Cache Bay Splash Park (Splash Pad)	55 Cache Street, Cache Bay, ON	Routine Inspection	29-May-18		Satisfactory - No Action(s) Taken

Cache Bay Splash Park (Splash Pad)	55 Cache Street, Cache Bay, ON	Routine Inspection	15-Aug-18		Satisfactory - No Action(s) Taken
Cache Bay Splash Park (Splash Pad)	55 Cache Street, Cache Bay, ON	Routine Inspection	11-Jun-19		Satisfactory - No Action(s) Taken
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	17-Jun-18	pH is within range of 7.2 to 7.8	Corrected During Inspection
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	13-Aug-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	13-Aug-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	12-Aug-19	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	12-Aug-19	Daily records completed, signed and available for viewing	Corrected During Inspection
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	12-Aug-19	Manual tests conducted ½ hr prior to opening: total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity	Corrected During Inspection
Cache Bay Tent & Trailer Park	74 Teal Road, Cache Bay ON POH 1G0	Routine Inspection	17-Aug-20	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Callander - Splash Pad	Main St, Callander ON	Routine Inspection	31-Jul-18		Satisfactory - No Action(s) Taken
Canada's Best Value Inn	48 Joseph Street, Parry Sound ON P2A 2G5	Complaint & Compliance	18-Sep-19	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Re-inspection Scheduled
Canada's Best Value Inn & Suite	48 Joseph Street, Parry Sound ON P2A 2G5	Complaint & Re-inspection	7-Nov-19		Satisfactory - No Action(s) Taken
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	23-Feb-18		Satisfactory - No Action(s) Taken
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	11-Jun-18	Sufficient supply of chemicals and testing devices	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	11-Jun-18	Total bromine (Br) residual at a minimum of 2mg/L (2.0ppm)	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	11-Jun-18	Premises is maintained free from every condition that may be a health hazard	Closure

Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Recirculation system of water facility is in good working condition	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Sufficient supply of chemicals and testing devices	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	pH is within range of 7.2 to 7.8	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Manual testing conducted once a day for pools with automatic sensing devices (pH, FAC and Total Cl or Br only)	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Daily records completed and signed	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	18-Sep-18	Premises is maintained free from every condition that may be a health hazard	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	pH is within range of 7.2 to 7.8	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	Manual testing conducted once a day for pools with automatic sensing devices (pH, FAC and Total Cl or Br only)	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	Safe storage and handling of all chemicals	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	Other records signed and completed	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	Safety equipment available and in good repair	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	4-Oct-18	Premises is maintained free from every condition that may be a health hazard	Closure

Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Safe storage and handling of all chemicals	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Daily records completed and signed	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Safety equipment available and in good repair	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Continuous operation of all equipment and chemical feeders	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Safe Storage and handling of all chemicals	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Daily records completed and signed	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	5-Oct-18	Safety equipment available and in good repair	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Re-inspection	29-Oct-18		Satisfactory - No Action(s) Taken
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	20-Feb-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	20-Feb-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	20-Feb-19	Daily records completed and signed	Re-inspection Scheduled
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	20-Jun-19	Pool, deck sanitary facility and adjoining areas kept in safe and sanitary condition	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	20-Jun-19	Pool, deck sanitary facility and adjoining areas kept in safe and sanitary condition	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	17-Sep-19	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	19-Feb-20	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	19-Feb-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection

Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Perimeter pool drain is kept free from debris	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Minimum amount of make-up water added daily	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Oxidation Reduction Potential (ORP) within range of 600-900 mV (if equipped with automatic sensing device)	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Written emergency and operational procedures & instructions available at the pool	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Perimeter pool drain is kept free from debris	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Minimum amount of make-up water added daily	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Oxidation Reduction Potential (ORP) within range of 600-900 mV (if equipped with automatic sensing device)	Corrected During Inspection



Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	25-Sep-20	Written emergency and operational procedures & instructions available at the pool	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	21-Dec-20	Total bromine (Br) residual within range of 2-4 ppm	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	21-Dec-20	pH is within range of 7.2 to 7.8	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	21-Dec-20	Total alkalinity within range of 80-120 ppm	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	21-Dec-20	Safety equipment available and in good repair	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	21-Dec-20	Premises is maintained free from every serious condition that may be a health hazard	Closure
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	11-Mar-21	pH is within range of 7.2 to 7.8	Corrected During Inspection
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	28-Jul-21		Satisfactory - No Action(s) Taken
Canada's Best Value Inn & Suites	48 Joseph Street, Parry Sound ON P2A 2G5	Routine Inspection	19-Oct-21	Minimum amount of make-up water added daily	Corrected During Inspection
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	4-Jun-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	13-Aug-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	13-Aug-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	25-Jun-19		Satisfactory - No Action(s) Taken
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	24-Jul-19	pH is within range of 7.2 to 7.8	Corrected During Inspection

Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	24-Jul-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	17-Jun-20		Satisfactory - No Action(s) Taken
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	19-Aug-20	pH is within range of 7.2 to 7.8	Corrected During Inspection
Cardinal Park and Marina	10518 Hwy 64 S, Lavigne ON POH 1R0	Routine Inspection	19-Aug-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Cardinal Park and Marina - Swimming Pool	10518 ON 64, Lavigne ON POH 1R0	Routine Inspection	9-Jun-21		Satisfactory - No Action(s) Taken
Cardinal Park and Marina - Swimming Pool	10518 ON 64, Lavigne ON POH 1R0	Routine Inspection	9-Aug-21		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	17-Jan-18		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	27-Jun-18		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	23-Jul-18		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	29-Oct-18		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	8-Feb-19		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	11-Jun-19		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	29-Jul-19	Recirculation system of water facility is in good working condition including automatic dosing device	Re-inspection Scheduled
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Re-inspection	12-Aug-19	Recirculation system of water facility is in good working condition including automatic dosing device	Re-inspection Scheduled
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	11-Nov-19		Satisfactory - No Action(s) Taken
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	16-Jan-20		Satisfactory - No Action(s) Taken

Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	30-Jun-20	Public pool has a designated operator	Re-inspection Scheduled
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	30-Jun-20	Free available chlorine (FAC) within range of 0.5 - 10 ppm	Closure
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	30-Jun-20	Stabilized free available chlorine (FAC) within range of 1 – 10 ppm (Outdoor Pools Only)	Closure
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	30-Jun-20	pH is within range of 7.2 to 7.8	Closure
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	30-Jun-20	Total alkalinity within range of 80-120 ppm	Closure
Caswell Resort Hotel Pool	77 Main Street, Sundridge ON P0A 1Z0	Routine Inspection	30-Jun-20	Written emergency and operational procedures & instructions available at the pool	Re-inspection Scheduled
Club Kodiak	1181 Pickeral & Jack Lake Rd, Burk's Falls ON P0A 1C0	Routine Inspection	25-Jun-18	Water clarity satisfactory/black disc clearly visible 9 m away	Closure
Club Kodiak	1181 Pickeral & Jack Lake Rd, Burk's Falls ON P0A 1C0	Routine Inspection	25-Jun-18	Black disc (150 mm in diameter) on white background affixed to bottom of pool at its deepest point	Closure
Club Kodiak	1181 Pickeral & Jack Lake Rd, Burk's Falls ON P0A 1C0	Re-inspection	29-Jun-18		Satisfactory - No Action(s) Taken
Club Kodiak	1181 Pickeral & Jack Lake Rd, Burk's Falls ON P0A 1C0	Routine Inspection	20-Jun-19		Satisfactory - No Action(s) Taken
Club Kodiak	1181 Pickeral & Jack Lake Rd, Burk's Falls ON P0A 1C0	Routine Inspection	30-Jul-19		Satisfactory - No Action(s) Taken
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	31-Jan-18		Satisfactory - No Action(s) Taken
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	23-Apr-18		Satisfactory - No Action(s) Taken
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	13-Nov-18	Daily records completed and signed	Corrected During Inspection
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	24-Apr-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection

Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	24-Apr-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	10-Jul-19		Satisfactory - No Action(s) Taken
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	9-Oct-19		Satisfactory - No Action(s) Taken
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	10-Dec-20	Other records signed and completed	Re-inspection Scheduled
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	10-Dec-20	Safety equipment available and in good repair	Re-inspection Scheduled
Comfort Inn	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	16-Jun-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Comfort Inn - Swimming Pool	11 Front Street, Sturgeon Falls ON P2B 3L3	Re-inspection	17-Dec-20		Satisfactory - No Action(s) Taken
Comfort Inn - Swimming Pool	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	8-Mar-21		Satisfactory - No Action(s) Taken
Comfort Inn - Swimming Pool	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	15-Jul-21		Satisfactory - No Action(s) Taken
Comfort Inn - Swimming Pool	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	20-Oct-21	Perimeter pool drain is kept free from debris	Corrected During Inspection
Comfort Inn Swimming Pool	11 Front Street, Sturgeon Falls ON P2B 3L3	Routine Inspection	10-Jul-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	29-May-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	23-Jul-18	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	23-Jul-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	2-Jul-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	12-Aug-19	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	12-Aug-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection

Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	12-Aug-19	Daily records completed, signed and available for viewing	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	17-Jun-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	19-Aug-20	pH is within range of 7.2 to 7.8	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	19-Aug-20	If not equipped with an automatic sensing device, manual tests conducted at least every 2 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Corrected During Inspection
Deluxe Camp	131 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	19-Aug-20	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-21	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Re-inspection Scheduled
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	7-Jul-21	Safety equipment available and in good repair	Re-inspection Scheduled
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	18-Aug-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	18-Aug-21	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	18-Aug-21	Other records signed and completed	Re-inspection Scheduled

Deluxe Camp - Swimming Pool	131 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	18-Aug-21	Safety equipment available and in good repair	Re-inspection Scheduled
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	10-Jul-19	Safety equipment available and in good repair	Re-inspection Scheduled
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	2-Jul-21	Perimeter pool drain is kept free from debris	Corrected During Inspection
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	2-Jul-21	Minimum amount of make-up water added daily	Corrected During Inspection
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	2-Jul-21	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Corrected During Inspection
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	2-Jul-21	pH is within range of 7.2 to 7.8	Corrected During Inspection
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	2-Jul-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Dillon Cove Marina and Resort Inc.	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	2-Jul-21	Required notice(s) are provided and accurate	Corrected During Inspection
Dillon Cove Marina resort	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	28-Jun-18	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Dillon Cove Marina resort	1 Parker Lane, Nobel ON P0G 1G0	Routine Inspection	28-Jun-18	Pool, deck sanitary facility and adjoining areas kept in safe and sanitary condition	Re-inspection Scheduled
Dillon Cove Marina resort	1 Parker Lane, Nobel ON P0G 1G0	Re-inspection	3-Jul-18		Satisfactory - No Action(s) Taken
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	2-Aug-18		Satisfactory - No Action(s) Taken
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	11-Jun-19		Satisfactory - No Action(s) Taken
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	12-Aug-19		Satisfactory - No Action(s) Taken

Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	23-Jun-21		Satisfactory - No Action(s) Taken
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	31-Aug-21	Water is maintained free from visible matter and contamination	Closure
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	31-Aug-21	Water clarity satisfactory	Closure
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	31-Aug-21	Total alkalinity within range of 80-120 ppm	Closure
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Re-inspection	2-Sep-21	Recirculation system of water facility is in good working condition including automatic dosing device	Re-inspection Scheduled
Dreany Haven Camp	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Re-inspection	2-Sep-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Dreany Haven Camp - Swimming Pool	RR 3-1859 Hwy 17 E, Corbeil ON POH1K0	Routine Inspection	26-Jun-20		Satisfactory - No Action(s) Taken
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	6-Jun-19		Satisfactory - No Action(s) Taken
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Complaint	15-Jul-19		Re-inspection Scheduled
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Re-inspection	24-Jul-19		Satisfactory - No Action(s) Taken
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	15-Aug-19	Free available chlorine (FAC) within range of 0.5 - 10 ppm	Corrected During Inspection
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	12-Jun-20	Depth markings present in appropriate locations (for all pools and spas >3 m in horizontal dimension)	Re-inspection Scheduled
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	12-Jun-20	Required notice(s) are provided and accurate	Re-inspection Scheduled
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Re-inspection	18-Jun-20		Satisfactory - No Action(s) Taken
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	28-Aug-20		Satisfactory - No Action(s) Taken
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	9-Jun-21	pH is within range of 7.2 to 7.8	Re-inspection Scheduled

Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	9-Jun-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	9-Jun-21	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Re-inspection	10-Jun-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Fairview Park & Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Re-inspection	11-Jun-21	pH is within range of 7.2 to 7.8	Corrected During Inspection
Fairview Park & Marina - Swimming Pool	395 Riverbend Rd, North Bay ON P1B 8Z4	Routine Inspection	26-Jul-21		Satisfactory - No Action(s) Taken
Fairview Park and Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	13-Jun-18		Satisfactory - No Action(s) Taken
Fairview Park and Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Routine Inspection	10-Aug-18	Safety equipment available and in good repair	Re-inspection Scheduled
Fairview Park and Marina	395 Riverbend Road, North Bay ON P1B 8Z4	Re-inspection	14-Aug-18		Satisfactory - No Action(s) Taken
Fish Tale Lodge	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	12-Jun-18		Satisfactory - No Action(s) Taken
Fish Tale Lodge	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	24-Jul-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection
Fish Tale Lodge	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	17-Jul-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Fish Tale Lodge	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	15-Aug-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Fish Tale Lodge	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	6-Jul-20	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Fish Tale Lodge	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	24-Aug-20	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	29-Jun-21	Minimum amount of make-up water added daily	Re-inspection Scheduled



Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	29-Jun-21	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Re-inspection Scheduled
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	29-Jun-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	29-Jun-21	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	29-Jun-21	Shower signs posted at each shower and every entrance to the deck used by bathers	Re-inspection Scheduled
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	29-Jun-21	Safety equipment available and in good repair	Corrected During Inspection
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	9-Aug-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	9-Aug-21	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Fish Tale Lodge - Swimming Pool	2597 Wolseley Bay Road, Noelville ON P0M 2N0	Routine Inspection	9-Aug-21	Required notice(s) are provided and accurate	Re-inspection Scheduled
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	9-Jul-18		Satisfactory - No Action(s) Taken
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	20-Aug-18		Satisfactory - No Action(s) Taken
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	26-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	26-Jun-19	Cyanuric acid is not greater than 60mg/L (60ppm)	Re-inspection Scheduled
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Re-inspection	12-Jul-19		Satisfactory - No Action(s) Taken
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	27-Aug-19	Daily records completed, signed and available for viewing	Corrected During Inspection

Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	28-Aug-20	Stabilized free available chlorine (FAC) within range of 1 – 10 ppm (Outdoor Pools Only)	Re-inspection Scheduled
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	15-Jul-21	Recirculation system of water facility is in good working condition including automatic dosing device	Re-inspection Scheduled
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Routine Inspection	15-Jul-21	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Re-inspection Scheduled
Franklin Motel & Trailer Park	444 Lakeshore Drive, North Bay ON P1A 2E1	Re-inspection	26-Jul-21		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	19-Jan-18		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	3-Aug-18		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	19-Sep-18		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	19-Dec-18		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	8-Mar-19		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	13-Jun-19	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Re-inspection	14-Jun-19		Satisfactory - No Action(s) Taken

Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	10-Sep-19	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	10-Sep-19	Safety equipment available and in good repair	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	17-Dec-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	17-Dec-19	Safety equipment available and in good repair	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	17-Dec-19	Aquatic instructor/coach has their applicable certification readily available to the MOH/PHI	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	26-Feb-20		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	26-Jun-20		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	23-Sep-20	pH is within range of 7.2 to 7.8	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	23-Sep-20	pH is within range of 7.2 to 7.8	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	15-Dec-20		Satisfactory - No Action(s) Taken
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	18-Mar-21	Free available chlorine (FAC) within range of 0.5 - 10 ppm	Closure
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Routine Inspection	18-Mar-21	pH is within range of 7.2 to 7.8	Closure
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Re-inspection	19-Mar-21	pH is within range of 7.2 to 7.8	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Re-inspection	19-Mar-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Grand Tappattoo Resort	30 Tapattoo Trail, Seguin ON P2A 0B2	Re-inspection	26-Mar-21		Satisfactory - No Action(s) Taken

Grand Tappattoo Resort	30 Tapatoo Trail, Seguin ON P2A 0B2	Routine Inspection	28-Sep-21	Minimum amount of make-up water added daily	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapatoo Trail, Seguin ON P2A 0B2	Routine Inspection	28-Sep-21	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapatoo Trail, Seguin ON P2A 0B2	Routine Inspection	28-Sep-21	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapatoo Trail, Seguin ON P2A 0B2	Routine Inspection	28-Sep-21	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapatoo Trail, Seguin ON P2A 0B2	Routine Inspection	28-Sep-21	Other records signed and completed	Re-inspection Scheduled
Grand Tappattoo Resort	30 Tapatoo Trail, Seguin ON P2A 0B2	Re-inspection	15-Oct-21		Satisfactory - No Action(s) Taken
Hampton Inn	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	22-Jan-18		Satisfactory - No Action(s) Taken
Hampton Inn	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	29-May-18		Satisfactory - No Action(s) Taken
Hampton Inn	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	9-Aug-18		Satisfactory - No Action(s) Taken
Hampton Inn	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	12-Oct-18		Satisfactory - No Action(s) Taken
Hampton Inn	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	26-Mar-19	Daily records completed and signed	Corrected During Inspection
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	20-Jun-19		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	12-Feb-21		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	14-Jul-21	Perimeter pool drain is kept free from debris	Re-inspection Scheduled
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	14-Jul-21	Safety equipment available and in good repair	Re-inspection Scheduled

Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Re-inspection	15-Jul-21		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	6-Oct-21	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Action
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	6-Oct-21	Daily records completed, signed and available for viewing	Action
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	6-Oct-21	Emergency telephone sign posted with complete list of emergency contacts	Re-inspection Scheduled
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Re-inspection	15-Oct-21		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	3-Sep-19		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	26-Nov-19	Daily records completed, signed and available for viewing	Corrected During Inspection
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	20-Feb-20	Daily records completed, signed and available for viewing	Corrected During Inspection
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	26-Jun-20	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	26-Jun-20	Safety equipment available and in good repair	Re-inspection Scheduled
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Re-inspection	28-Aug-20		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	17-Sep-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Re-inspection	23-Sep-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Re-inspection	25-Sep-20		Satisfactory - No Action(s) Taken
Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	18-Nov-20		Satisfactory - No Action(s) Taken

Hampton Inn by Hilton North Bay	950 McKeown Avenue, North Bay ON P1B 9P3	Routine Inspection	18-Nov-20		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	23-Jan-18	pH is within range of 7.2 to 7.8	Corrected During Inspection
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	29-May-18	Total bromine (Br) residual at a minimum of 2mg/L (2.0ppm)	Corrected During Inspection
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	9-Aug-18		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	25-Oct-18		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	10-Jun-19	Total bromine (Br) residual at a minimum of 2mg/L (2.0ppm)	Closure
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	10-Jun-19	pH is within range of 7.2 to 7.8	Re-inspection Scheduled
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	10-Jun-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Re-inspection	11-Jun-19		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	14-Jan-21	Total bromine (Br) residual within range of 2-4 ppm	Closure
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	14-Jan-21	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	14-Jan-21	Emergency telephone is present and operational	Closure
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Re-inspection	15-Jan-21		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	15-Jun-21		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	6-Oct-21	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	11-Sep-19	Public pool has a designated operator	Re-inspection Scheduled
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	11-Sep-19	Total bromine (Br) residual within range of 2-4 ppm	Closure
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	11-Sep-19	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled

Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	11-Sep-19	Public pool has a designated operator	Re-inspection Scheduled
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	11-Sep-19	Total bromine (Br) residual within range of 2-4 ppm	Closure
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	11-Sep-19	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Re-inspection	30-Sep-19		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Re-inspection	30-Sep-19		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	25-Nov-19		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	12-Feb-20		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Routine Inspection	16-Jun-20		Satisfactory - No Action(s) Taken
Harbourside Condo	155 Timmins Street, North Bay ON P1B 4K2	Re-inspection	17-Sep-20		Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	1-Mar-18	Safe storage and handling of all chemicals	Corrected During Inspection
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	30-Aug-18		Corrected During Inspection
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	30-Aug-18		Corrected During Inspection
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	30-Aug-18		Corrected During Inspection
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	10-Dec-18		Closure
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Re-inspection	14-Dec-18		Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	13-Feb-19	Free available chlorine (FAC) at a minimum of 0.5mg/L (0.5ppm)	Corrected During Inspection
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	4-Sep-19	pH is within range of 7.2 to 7.8	Corrected During Inspection

Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	26-Nov-19	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	26-Nov-19	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	10-Feb-20		Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	30-Jun-20		Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Re-inspection	29-Oct-20		Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	22-Mar-21	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	22-Mar-21	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Re-inspection	25-Mar-21		Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	16-Jul-21	pH is within range of 7.2 to 7.8	Satisfactory - No Action(s) Taken
Holiday Inn Express Hotel & Suites	1325 Seymour Street, North Bay ON P1B 9V6	Routine Inspection	18-Oct-21		Satisfactory - No Action(s) Taken
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	22-Jan-18		Satisfactory - No Action(s) Taken
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	12-Nov-18		Satisfactory - No Action(s) Taken



Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	29-Jan-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	29-Jan-19	Deck and walls maintained in a sanitary condition and free from hazards	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	24-Apr-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	24-Apr-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	24-Apr-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	24-Apr-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	10-Jul-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	7-Oct-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	7-Oct-19	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	20-Jan-20	Emergency telephone is present and operational	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	20-Jan-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	10-Dec-20	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled

Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	10-Dec-20	Other records signed and completed	Re-inspection Scheduled
Homewood Suites	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	10-Dec-20	Safety equipment available and in good repair	Re-inspection Scheduled
Homewood Suites by Hilton	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	30-Apr-18		Satisfactory - No Action(s) Taken
Homewood Suites by Hilton	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	16-Jun-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Homewood Suites by Hilton - Swimming Pool	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	16-Mar-21		Satisfactory - No Action(s) Taken
Homewood Suites by Hilton - Swimming Pool	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	16-Jul-21	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Homewood Suites by Hilton - Swimming Pool	495 Oak Street W, North Bay ON P1B 2T3	Re-inspection	20-Jul-21		Satisfactory - No Action(s) Taken
Homewood Suites by Hilton - Swimming Pool	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	20-Oct-21	If equipped with an automatic sensing device, parameters checked at least every 4 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled
Homewood Suites by Hilton - Swimming Pool	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	20-Oct-21	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Homewood Suites by Hilton - Swimming Pool	495 Oak Street W, North Bay ON P1B 2T3	Routine Inspection	20-Oct-21	Other records signed and completed	Re-inspection Scheduled
Joli Voyageur Resort & Campground - Swimming Pool	95 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	21-Jul-21	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Joli Voyageur Resort & Campground - Swimming Pool	95 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	21-Jul-21	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Joli Voyageur Resort & Campground - Swimming Pool	95 Caron Rd, Lavigne ON P0H 1R0	Routine Inspection	21-Jul-21	Safety equipment available and in good repair	Re-inspection Scheduled
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	12-Jun-18		Satisfactory - No Action(s) Taken
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	23-Jul-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Corrected During Inspection

Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	2-Jul-19		Satisfactory - No Action(s) Taken
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	12-Aug-19	pH is within range of 7.2 to 7.8	Corrected During Inspection
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	12-Aug-19	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	14-Jul-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	14-Jul-20	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Routine Inspection	17-Aug-20	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled
Joli Voyageur Resort and Campground	95 Caron Road, Lavigne ON P0H 1R0	Re-inspection	19-Aug-20	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Jolly Inn Rodgers Inn & Resort	1 J R LN, Seguin ON P2A 2W8	Routine Inspection	28-Jul-21		Satisfactory - No Action(s) Taken
Make a Splash for Stacey Splash Pad	Sundridge Beach, Sundridge ON P0A 1Z0	Routine Inspection	23-Jul-18		Satisfactory - No Action(s) Taken
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	27-Jun-18		Satisfactory - No Action(s) Taken
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	25-Jul-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Re-inspection Scheduled
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	25-Jul-18	Daily records completed and signed	Re-inspection Scheduled
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Re-inspection	13-Aug-18		Satisfactory - No Action(s) Taken
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	30-Jul-19		Satisfactory - No Action(s) Taken
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	17-Sep-19		Satisfactory - No Action(s) Taken
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	26-Jun-20		Satisfactory - No Action(s) Taken
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	24-Aug-20	Every bather shall take a cleansing shower/bath using soap and warm water before entering deck	Re-inspection Scheduled
Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	24-Aug-20	Cyanuric acid not greater than 60 ppm	Re-inspection Scheduled

Northridge Inn and Resort	712 Bernard Lake Road S, Sundridge ON P0A 1Z0	Routine Inspection	24-Aug-20	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Re-inspection Scheduled
Northridge Inn and Resort	712 South Bernard Lake Road, Sundridge, ON P0A 1X0	Routine Inspection	4-Jun-21	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Ontario Northland Apartments	665 Oak Street East, North Bay ON P1B 8E3	Routine Inspection	25-Jun-18		Satisfactory - No Action(s) Taken
Ontario Northland Apartments	665 Oak Street East, North Bay ON P1B 8E3	Routine Inspection	28-Aug-19	Equalizer fittings rendered inoperable	Corrected During Inspection
Ontario Northland Apartments	665 Oak Street East, North Bay ON P1B 8E3	Routine Inspection	28-Aug-19	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Ontario Northland Apartments	665 Oak Street East, North Bay ON P1B 8E3	Routine Inspection	6-Jul-20	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Ontario Northland Apartments	665 Oak Street East, North Bay ON P1B 8E3	Routine Inspection	17-Jun-21		Satisfactory - No Action(s) Taken
Ontario Northland Apartments	665 Oak Street East, North Bay ON P1B 8E3	Routine Inspection	3-Jun-19		Satisfactory - No Action(s) Taken
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	17-Aug-18	Written emergency, and operational procedures & instructions available at the pool	Re-inspection Scheduled
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	7-Aug-19	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Re-inspection Scheduled
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	7-Aug-19	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Re-inspection Scheduled
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	7-Aug-19	Safe storage, handling and sufficient supply of all chemicals	Re-inspection Scheduled
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	17-Jun-20	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Corrected During Inspection

Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	17-Jun-20	Perimeter pool drain is kept free from debris	Corrected During Inspection
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	17-Jun-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	17-Jun-20	Safe storage, handling and sufficient supply of all chemicals	Corrected During Inspection
Parry Sound KOA Campground	276 Rankin Lake Road, Seguin ON P2A 0B2	Routine Inspection	9-Jun-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-18		Satisfactory - No Action(s) Taken
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	17-Sep-18		Satisfactory - No Action(s) Taken
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Black disc (150 mm in diameter) on white background affixed to bottom of pool at its deepest point	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Make-up water requirements met (Spa>4000 litres)	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Daily records completed and signed	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Other records signed and completed	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Depth markings present in appropriate locations	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Shallow Water/No Diving Caution (pool water depth < 2.5 m)	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	25-Jun-19	Depth markings present in appropriate locations	Re-inspection Scheduled
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Water is maintained free from visible matter and contamination	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Minimum amount of make-up water added daily	Corrected During Inspection

Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Daily records completed, signed and available for viewing	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	22-Jun-20	Other records signed and completed	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	30-Jun-21	Minimum amount of make-up water added daily	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	30-Jun-21	Exposed pipes are identified by coloured bands (at least 25 millimetres wide spaced along the piping at intervals not greater than 1.20 metres) or by painting the entire outer surface of the pipe (Yellow-Chlorine, Green-Potable Water)	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	30-Jun-21	pH is within range of 7.2 to 7.8	Corrected During Inspection
Pleasant Cove Resort	97 North Shore Road, Pointe au Baril ON P0G 1K0	Routine Inspection	30-Jun-21	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Powassan Public Pool	355 Edward Street North, Powassan ON P0H 1Z0	Routine Inspection	25-Jun-18	Water meter registers the volume of make-up water	Re-inspection Scheduled
Powassan Public Pool	355 Edward Street N, Powassan ON P0H 1Z0	Routine Inspection	6-Jun-19		Satisfactory - No Action(s) Taken
Powassan Public Pool	355 Edward Street North, Powassan ON P0H 1Z0	Routine Inspection	23-Aug-19	Equalizer fittings rendered inoperable	Corrected During Inspection
Quality Inn - Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	13-Aug-20		Satisfactory - No Action(s) Taken

Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	5-Mar-19	Exposed piping within pool enclosure is properly colour-coded	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	5-Mar-19	Manual testing conducted once a day for pools with automatic sensing	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Re-inspection	1-Apr-19	Manual testing conducted once a day for pools with automatic sensing devices (pH, FAC and Total Cl or Br only)	Corrected During Inspection
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	25-Apr-19		Satisfactory - No Action(s) Taken
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	12-Sep-19	Recirculation system of water facility is in good working condition including automatic dosing device	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	12-Sep-19	If equipped with an automatic sensing device, parameters checked at least	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	22-Jan-20	Black disc (150 mm in diameter) on white background affixed to bottom of	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	22-Jan-20	If equipped with an automatic sensing device, parameters checked at least	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	12-Dec-20	Recirculation system of water facility is in good working condition including	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	12-Dec-20	If equipped with an automatic sensing device, parameters checked at least	Re-inspection Scheduled
Quality Inn- Swimming Pool	1525 Seymour Street, North Bay ON P1B 8G4	Routine Inspection	20-Jul-21	Recirculation system of water facility is in good working condition including	Re-inspection Scheduled
Quiet Bay Log Motel & Café	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	12-Jun-18		Satisfactory - No Action(s) Taken
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Perimeter pool drain is kept free from debris	Corrected During Inspection
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Equalizer fittings rendered inoperable	Closure
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Minimum amount of make-up water added daily	Re-inspection Scheduled
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Cyanuric acid not greater than 60 ppm	Closure

Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Proper test kit is available for use to determine water chemistry	Re-inspection Scheduled
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	If not equipped with an automatic sensing device, manual tests conducted at least every 2 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Re-inspection Scheduled
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	9-Aug-19	Other records signed and completed	Re-inspection Scheduled
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Re-inspection	15-Aug-19	Cyanuric acid not greater than 60 ppm	Corrected During Inspection
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Re-inspection	15-Aug-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Quiet Bay Log Motel & Café (Pool)	5333 Highway 124, Magnetawan ON P0A 1P0	Routine Inspection	26-Jun-20	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	26-Jan-18		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-Jun-18		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Sep-18	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Sep-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Sep-18	Free available chlorine (FAC) at a minimum of 0.5mg/L (0.5ppm)	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Water is maintained free from visible matter and contamination	Re-inspection Scheduled



Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	21-Dec-18	pH is within range of 7.2 to 7.8	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	27-Dec-18	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	27-Dec-18	Cyanuric acid is not greater than 60mg/L (60ppm)	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	27-Dec-18	Premises is maintained free from every condition that may be a health hazard	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	11-Jan-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-19	Sanitary facilities maintained in a safe and sanitary condition	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	25-Mar-19	Water facility inaccessible when closed	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	25-Mar-19	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	25-Mar-19	Cyanuric acid is not greater than 60mg/L (60ppm)	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	25-Mar-19	Daily records completed and signed	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	25-Mar-19	Emergency telephone sign posted with complete list of emergency contacts	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-May-19	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Re-inspection Scheduled

Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	28-May-19	Stabilized free available chlorine (FAC) at a minimum of 1.0mg/L (1.0ppm) when used with cyanurate	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	29-May-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	29-May-19		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Nov-19	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Nov-19	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Nov-19	Emergency telephone sign posted with complete list of emergency contacts	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	5-Nov-19	Safety equipment available and in good repair	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Public pool has a designated operator	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Minimum amount of make-up water added daily	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Stabilized free available chlorine (FAC) within range of 1 – 10 ppm (Outdoor Pools Only)	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	If not equipped with an automatic sensing device, manual tests conducted at least every 2 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Daily records completed, signed and available for viewing	Closure

Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Other records signed and completed	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	19-Feb-20	Premises is maintained free from every serious condition that may be a health hazard	Closure
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	14-Aug-20	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Corrected During Inspection
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	14-Aug-20	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	18-Aug-20		Satisfactory - No Action(s) Taken
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	10-Dec-20	Pool, deck and walls maintained in a sanitary condition, safe and free from hazards	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	10-Dec-20	Perimeter pool drain is kept free from debris	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	10-Dec-20	Water is maintained free from visible matter and contamination	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	10-Dec-20	Daily records completed, signed and available for viewing	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	10-Dec-20	Required notice(s) are provided and accurate	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Routine Inspection	10-Dec-20	Safety equipment available and in good repair	Re-inspection Scheduled
Ramada Pinewood Park Resort North Bay	201 Pinewood Park Drive, North Bay ON P1B 8Z4	Re-inspection	17-Dec-20	Required notice(s) are provided and accurate	Corrected During Inspection
Rocky Crest Pool	20 Barnwood Drive, Mactier ON P0C 1H0	Routine Inspection	12-Aug-20		Satisfactory - No Action(s) Taken
Rocky Crest Pool	20 Barnwood Drive MacTier ON P0C 1H0	Routine Inspection	1-Jun-21	Stabilized free available chlorine (FAC) within range of 1 – 10 ppm (Outdoor Pools Only)	Corrected During Inspection
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	24-May-18	Daily records completed and signed	Re-inspection Scheduled
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	24-May-18	Class B Pool – Safety supervision signs posted in letters at least 25 mm high	Re-inspection Scheduled

Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	15-Jun-18	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	15-Jun-18	Pool, deck sanitary facility and adjoining areas kept in safe and sanitary condition	Re-inspection Scheduled
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	15-Jun-18	Water is maintained free from visible matter and contamination	Re-inspection Scheduled
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	27-Sep-18		Satisfactory - No Action(s) Taken
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	27-Sep-18		Satisfactory - No Action(s) Taken
Rocky Crest Resort	20 Barnwood Drive, Mactier ON P0C 1H0	Routine Inspection	17-May-19	Deck and walls maintained in a sanitary condition and free from hazards	Corrected During Inspection
Rocky Crest Resort	20 Barnwood Drive, Mactier ON P0C 1H0	Routine Inspection	17-May-19	Exposed piping within pool enclosure is properly colour-coded	Re-inspection Scheduled
Rocky Crest Resort	20 Barnwood Drive, Mactier ON P0C 1H0	Routine Inspection	17-May-19	Daily records completed and signed	Re-inspection Scheduled
Rocky Crest Resort	149 Hamer Bay Road, Mactier ON P0C 1H0	Routine Inspection	29-Aug-19		Satisfactory - No Action(s) Taken
Rocky Crest Resort	20 Barnwood Drive, Mactier ON P0C 1H0	Routine Inspection	10-Jun-20		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing, Nipissing Village ON P0H 1W0	Routine Inspection	12-Jun-18		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing, Nipissing Village ON P0H 1W0	Routine Inspection	20-Aug-18		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing, Nipissing Village ON P0H 1W0	Routine Inspection	18-Jun-19		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing, Nipissing Village ON P0H 1W0	Routine Inspection	28-Aug-19		Satisfactory - No Action(s) Taken

South River Resort	239 Chapman's Landing, Nipissing Village ON POH 1W0	Routine Inspection	18-Jun-20		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing, Nipissing Village ON POH 1W0	Routine Inspection	31-Aug-20		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing, Nipissing Village ON POH 1W0	Routine Inspection	15-Jun-21		Satisfactory - No Action(s) Taken
South River Resort	239 Chapman's Landing Nipissing Village ON POH 1W0	Routine Inspection	26-Jul-21		Satisfactory - No Action(s) Taken
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Water clarity satisfactory/black disc clearly visible 9 m away	Closure
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Sufficient supply of chemicals and testing devices	Re-inspection Scheduled
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Free available chlorine (FAC) at a minimum of 0.5mg/L (0.5ppm)	Closure
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	pH is within range of 7.2 to 7.8	Closure
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Manual testing conducted once a day for pools with automatic sensing devices (pH, FAC and Total Cl or Br only)	Re-inspection Scheduled
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Daily records completed and signed	Re-inspection Scheduled
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON POA 1C0	Routine Inspection	2-Feb-18	Records retained for one year	Re-inspection Scheduled

Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON P0A 1C0	Routine Inspection	2-Feb-18	Safety equipment available and in good repair	Re-inspection Scheduled
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON P0A 1C0	Routine Inspection	2-Feb-18	Class B Pool – Safety supervision signs posted in letters at least 25 mm high	Re-inspection Scheduled
Spirit of the North Pool	2159 Pickerel & Jack Lake Rd, Burks Falls ON P0A 1C0	Routine Inspection	2-Feb-18	Premises is maintained free from every condition that may be a health hazard	Closure
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	19-Jun-19	Other records signed and completed	Corrected During Inspection
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	31-Mar-21		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	6-Jul-21	Other records signed and completed	Action
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	13-Oct-21		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	22-Jan-18	pH is within range of 7.2 to 7.8	Corrected During Inspection
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	22-Jan-18	Black disc (150 mm in diameter) on white background affixed to bottom of pool at its deepest point	Re-inspection Scheduled
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	29-Jan-18	pH is within range of 7.2 to 7.8	Closure
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	29-Jan-18	Black disc (150 mm in diameter) on white background affixed to bottom of pool at its deepest point	Closure
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	30-Jan-18		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	29-May-18	Other records signed and completed	Re-inspection Scheduled
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	1-Jun-18		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	9-Aug-18		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	17-Oct-18	pH is within range of 7.2 to 7.8	Re-inspection Scheduled

St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	17-Oct-18	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	18-Oct-18		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	11-Mar-19	Total alkalinity at a minimum of 80mg/L (80ppm)	Re-inspection Scheduled
St. Joseph's Motherhouse	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	12-Mar-19		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	4-Sep-19		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	25-Nov-19	Total alkalinity within range of 80-120 ppm	Re-inspection Scheduled
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	6-Dec-19		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	25-Feb-20		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	26-Jun-20	pH is within range of 7.2 to 7.8	Re-inspection Scheduled
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Re-inspection	30-Jun-20		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	18-Nov-20		Satisfactory - No Action(s) Taken
St. Joseph's Motherhouse - Indoor Pool	2025 Main Street West, North Bay ON P1B 2X6	Routine Inspection	18-Nov-20		Satisfactory - No Action(s) Taken
Stonegate 1	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	17-May-18		Satisfactory - No Action(s) Taken
Stonegate I	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	7-Jun-19		Satisfactory - No Action(s) Taken
Stonegate I	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	29-Aug-19	Total bromine (Br) residual within range of 2-4 ppm	Corrected During Inspection
Stonegate I	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	29-Aug-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection

Stonegate I	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	29-Aug-19	If not equipped with an automatic sensing device, manual tests conducted at least every 2 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Corrected During Inspection
Stonegate I	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	29-Aug-19	Other records signed and completed	Corrected During Inspection
Stonegate I	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	19-Jun-20	Required notice(s) are provided and accurate	Corrected During Inspection
Stonegate I - Swimming Pool	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	9-Jun-21		Satisfactory - No Action(s) Taken
Stonegate I - Swimming Pool	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	26-Aug-21	If not equipped with an automatic sensing device, manual tests conducted at least every 2 hours until the daily use period has ended (total alkalinity, pH value, free available chlorine, total chlorine or bromine residual and water clarity)	Corrected During Inspection
Stonegate I - Swimming Pool	600-116 Blair Street, North Bay ON P1A 4E7	Routine Inspection	26-Aug-21	Safety equipment available and in good repair	Corrected During Inspection
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	21-Feb-18		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-Jun-18	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-Jun-18	Water is maintained free from visible matter and contamination	Re-inspection Scheduled
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-Jun-18	Other records signed and completed	Re-inspection Scheduled
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Re-inspection	14-Jun-18		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	6-Sep-18	Other records signed and completed	Corrected During Inspection



Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	15-Feb-19	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	7-May-19	Deck and walls maintained in a sanitary condition and free from hazards	Re-inspection Scheduled
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	24-Jul-19	Total alkalinity within range of 80-120 ppm	Corrected During Inspection
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	4-Nov-19		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Re-inspection	29-Nov-19		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Jan-20		Satisfactory - No Action(s) Taken
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Jan-20	Clock installed in conspicuous location	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Jan-20	Free available chlorine (FAC) or total bromine within range of 5 - 10 ppm	Corrected During Inspection
Sturgeon Falls Pool - Spa	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Jan-20	Hydro-massage jet fittings equipped with timing device	Re-inspection Scheduled
Sturgeon Falls Pool- Wading Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	4-Nov-19	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Sturgeon Falls Pool- Wading Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Jan-20	Free available chlorine (FAC) or Total Bromine maintained within the range of 5 – 10 ppm	Corrected During Inspection
Sturgeon Falls Pool- Wading Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Jan-20	Total alkalinity is within range of 80-120 ppm	Corrected During Inspection
Sturgeon Falls Spray Park (Splash Pad)	Lot 82 and Lot 83 Plan 12, Sturgeon Falls ON P2B 3L3	Routine Inspection	29-May-18		Satisfactory - No Action(s) Taken
Sturgeon Falls Spray Park (Splash Pad)	Lot 82 and Lot 83 Plan 12, Sturgeon Falls ON P2B 3L3	Routine Inspection	15-Aug-18		Satisfactory - No Action(s) Taken
Sturgeon Falls Spray Park (Splash Pad)	Lot 82 and Lot 83 Plan 12, Sturgeon Falls ON P2B 3L3	Routine Inspection	11-Jun-19		Satisfactory - No Action(s) Taken
Sturgeon Falls Swimming Pool	219 O'Hara Street, Sturgeon Falls ON P2B 1A2	Routine Inspection	29-Nov-18		Satisfactory - No Action(s) Taken